

ATTORNEY'S DOCKET:
073338.0178

PATENT NO:
6,977,600 B2

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee: Jiang, et al.
U.S. Patent No.: 6,977,600 B2
Issue Date: December 20, 2005
Serial No.: 10/821,034
Filing Date: April 8, 2004
Title: *Determining Analog Error Using Parallel Path Sampling*

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450


Dear Sir:

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER 37 CFR § 1.322

It is respectfully requested that a Certificate of Correction be issued in accordance with the enclosed Form PTO-1050. The error involved is believed to be a Patent Office error, and it is believed that no fee is due in association with this request for a Certificate of Correction. However, the Commissioner is hereby authorized to charge any fees or credit any overpayments to Deposit Account No. 02-0384 of Baker Botts L.L.P.

It is respectfully submitted that a significant error is present in the printed patent, that correction thereof in accordance with the enclosed Form PTO-1050 is required in order that no misunderstanding will occur.

Respectfully submitted,
BAKER BOTTS L.L.P.
Attorneys for Applicant



Barton E. Showalter
Reg. No. 38,302

Date: Dec 7, 2006
BAKER BOTTS L.L.P.
2001 Ross Avenue, Suite 600
Dallas, Texas 75201-2980
Phone: (214) 953-6509
(bjs)

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Patent No.: 6,977,600 B2
Dated: December 20, 2005
Inventor(s): Jiang, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4, Line 57, after “embodiments”, delete “nts”.

Mailing Address of Sender:
Baker Botts L.L.P.
2001 Ross Avenue, Suite 600
Dallas, Texas 75201-2980

Patent No. 6,977,600 B2

Form PTO-1050